R.T. Time (10 nsec / small div)

2.5 us   2.6 us   2.7 us   2.8 us   2.9 us

— from HF3B-100.s1p (pre-arc-damage, 10 April 2015)

— from 20Aug3B.s1p (check of FINALLY-repaired damage, 20 Aug)

— pre-repair_2nd-arc (antenna instead of short at end) (8.543m O.W.)

Dana Whitlow
18 Sept 2015
new_mix_narr_2nd_arc.fc7

HF3B-100.s1p (pre-1st-arc file)
HF3B-x1x.s1p (repaired post-1st-arc file)
23jun3b.s1p (retry later to see any changes)
01Jul3b.s1p (a week later)
20Aug3B.s1p (following wholesale repl of last 50 ft or so of line)
farlin4c.exe
plot bin limits 8300:9520
goodnarr.fc7
newbadnarr.fc7
23Jun3B.fc7
tl4sep18.s1p
tl4sep18.fc7
01Jul3B.fc7
20Aug3B.fc7