




CW Spins.  $Z_a=15$ ,  $A_z: -90.$  to  $0.$  Motors 11,12




Motors 51,52




Motors 41,42




Motors 81,82




CW Spins.  $Z_a=15$ ,  $Az$ : 0. to 90. Motors 11,12




Motors 51,52




Motors 41,42




Motors 81,82




CW Spins.  $Z_a=15$ ,  $A_z$ : 90. to 180. Motors 11,12




Motors 51,52




Motors 41,42




Motors 81,82




CW Spins.  $Z_a=15$ ,  $A_z$ : 180. to 270. Motors 11,12



Motors 51,52



Motors 41,42



Motors 81,82

