



# KLYSTRON AGING SET-UP



CAPACITOR FAULT STATUS TO K59 DWG 430\_106 p2  
THIS LINE IS GROUNDED IF CURRENT THROUGH M9 IS TOO LOW

TURN OFF MODULATOR  
VIA BREAKER NEAR  
DOOR OF KLYSTRON VAULT

430 TRANSMITTER  
DWG. 430\_AGE  
TITLE: CAPACITOR BANK KLYSTRON AGING SET-UP  
AND BEAM VOLTAGE CIRCUITRY  
DRAWN 12-98 TO REPLACE D349C105

file:430\_105.ecw jbh 12-17-98 rev 8-7-02  
file:430\_age.ecw jbh 2-24-03