




14sep15 hf rf monitor cable loss (from S11)



smooth by 3.25 Mhz to remove ripple



full freq range measured



smooth by 3.25 Mhz to remove ripple

